



Product Service

CERTIFICATE

No. B 10 07 68829 013

Holder of Certificate: Tong Yang Industry Co. Ltd.
TONG YANG GROUP
*Tong Yang Industry Co. Ltd.*98. An Ho Rd.; Sec. 2
70967 Tainan
TAIWAN
Production Facility(ies): 68829

Certification Mark:

Product: Adhered units for vehicles, plastic parts
Passenger car bumpers

Model(s): PP
(Part No. see attachment)


Parameters: Aftermarket bumper for passenger car made of PP
Fittment and shape equal to original equipment

Tested according to: PPP 90015:2009

The product was tested on a voluntary basis and complies with the essential requirements. The certification mark shown above can be affixed on the product. It is not permitted to alter the certification mark in any way. In addition the certification holder must not transfer the certificate to third parties. See also notes overleaf.

Test report no.: 09-00040-CP-GBM-05

Date, 2010-07-22


(Max Höhler)

Page 1 of 2





Product Service

Attachment to Certificate B 10 07 68829 013

Holder of Certificate: Tong Yang Industry Co. Ltd.

Passenger car bumpers Part No.:

| | | | | |
|------------|------------|------------|------------|------------|
| AA04008BA | FD04310BA | FT07028GA | PG04028MAR | TY04255MBL |
| AA04009BA | FD07247GA | FT07032GA | PG04028MBL | TY04255MBR |
| BM04028BA | FD07247GB | FT07033GA | PG04028MBR | TY04267BA |
| BZ04028BA | FD07258GA | FT99006CAL | PG04029BA | TY99064CAL |
| BZ04034BA | FD07280GA | FT99006CAR | RN04044BA | TY99064CAR |
| BZ04035BA | FD99157CAL | FT99008CAL | RN04044BB | VW04065MAL |
| BZ04035MAL | FD99157CAR | FT99008CAR | RN04046BA | VW04065MAR |
| BZ04035MAR | FD99159CAL | FT99009CAL | RN04046MAL | VW04090MAL |
| BZ04051BA | FD99159CAR | FT99009CAR | RN04046MAR | VW04090MAR |
| BZ04051BD | FD99160CAL | LN04003MA | RN04052BA | VW04101BA |
| CT04016BA | FD99160CAR | LN04003MB | RN04052BB | VW04101MAL |
| CT04016MAL | FT04029BB | LN04005BA | RN05007VA | VW04101MAR |
| CT04016MAR | FT04029BC | LN04006BA | RN07037GA | VW04104MAL |
| CT04017MA | FT04029BD | OP04042BA | RN99035CAL | VW04104MAR |
| CT04017MB | FT04031MA | OP04043BA | RN99035CAR | VW04107BA |
| CT04018BA | FT04044BA | OP04043BB | SD04007MAL | VW04108BA |
| CT07012GA | FT04045BA | OP04043BC | SD04007MAR | VW04108MA |
| CT99003CAL | FT04045MAC | OP04043BD | SD04009BA | VW04108MB |
| CT99003CAR | FT04045MAL | OP04055BA | SD04009BB | VW04116BA |
| CT99004CAL | FT04045MAR | OP04056BA | SD04010BA | VW04119MAL |
| CT99004CAR | FT04046BA | OP04057BA | SD04010BB | VW04119MAR |
| DS04250BA | FT04046BB | OP04059BA | SD04011BA | VW05010VA |
| DS04250BB | FT04046PAL | OP04062BA | SD04011MAL | VW05012VA |
| DS04255BA | FT04046PAR | OP07026GA | SD04011MAR | VW05013VA |
| DS04255BB | FT04046PBL | OP07029GA | SD07005GAC | VW05014VA |
| DS04256BA | FT04046PBR | OP99014CAL | SD07005GAL | VW05015VA |
| DS04256BB | FT04047BA | OP99014CAR | SD07005GAR | VW07069GA |
| DS04275BA | FT04048BA | OP99014CBL | SD07006GA | VW07072GA |
| DS07287GA | FT04049BA | OP99014CBR | SD07013GA | VW07077GA |
| FD04249BA | FT04049BB | OP99015CAL | ST04012BA | VW99030CAL |
| FD04258BA | FT04050BA | OP99015CAR | ST04013BA | VW99030CAR |
| FD04261BA | FT05001VA | PG04024BA | ST05002VA | VW99035CAL |
| FD04261MAL | FT05002VA | PG04024BB | TY04255BA | VW99035CAR |
| FD04261MAR | FT07018GA | PG04028BA | TY04255MAL | |
| FD04306BA | FT07026GA | PG04028MAL | TY04255MAR | |