



Product Service

CERTIFICATE

No. B 12 04 68829 035

Holder of Certificate: Tong Yang Industry Co. Ltd.

 TONG YANG GROUP
 Tong Yang Industry Co. Ltd.

 98. An Ho Rd.; Sec. 2
 70967 Tainan
 TAIWAN

Production Facility(ies): 68829

Certification Mark:

Product: Adhered units for vehicles, plastic parts
 Passenger car bumpers

Model(s): PP
 (Part No. see attachment)

Parameters: Aftermarket bumper and grills for passenger car made of PP
 Fittment and shape equal to original equipment

Tested according to: PPP 90015:2009

The product was tested on a voluntary basis and complies with the essential requirements. The certification mark shown above can be affixed on the product. It is not permitted to alter the certification mark in any way. In addition the certification holder must not transfer the certificate to third parties. See also notes overleaf.

Test report no.: 09-00040-CP-GBM-11

Date, 2012-04-04

(Max Höhler)

Page 1 of 2





Product code:

Product Service

| | | | | |
|------------|------------|------------|------------|------------|
| AA04008BA | DS04281BA | FT04049BB | PG04028MAR | TY04255MBR |
| AA04009BA | DS07287GA | FT04050BA | PG04028MBL | TY04267BA |
| AA04010BA | DS99088CAL | FT04055BA | PG04028MBR | TY04268BA |
| AD04025BA | DS99088CAR | FT04059BC | PG04029BA | TY05032VAL |
| AD04032BA | FD04249BA | FT04059BD | PG04030BA | TY05032VAR |
| AT04015BA | FD04258BA | FT04059MA | RN04044BA | TY07350GA |
| BM04028BA | FD04261BA | FT05001VA | RN04044BB | TY07404GA |
| BM04032BA | FD04261MAL | FT05002VA | RN04046BA | TY99064CAL |
| BM04039BA | FD04261MAR | FT07018GA | RN04046MAL | TY99064CAR |
| BM04039BB | FD04305BA | FT07026GA | RN04046MAR | VV04009BA |
| BM04047BA | FD04306BA | FT07028GA | RN04052BA | VW04065MAL |
| BM04047BB | FD04307BA | FT07032GA | RN04052BB | VW04065MAR |
| BZ04028BA | FD04307PAL | FT07033GA | RN05007VA | VW04084BA |
| BZ04034BA | FD04307PAR | FT07041GA | RN07037GA | VW04085BB |
| BZ04035BA | FD04307PBL | FT07042GA | RN07050GA | VW04090MAL |
| BZ04035MAL | FD04307PBR | FT07043GA | RN07051GA | VW04090MAR |
| BZ04035MAR | FD04310BA | FT07043GB | RN99035CAL | VW04101BA |
| BZ04051BA | FD04319BA | FT07044GA | RN99035CAR | VW04101MAL |
| BZ04051BB | FD04325BA | FT07044GB | SD04007MAL | VW04101MAR |
| BZ04051BD | FD04353BA | FT99006CAL | SD04007MAR | VW04104MAL |
| BZ04053BA | FD04354BA | FT99006CAR | SD04008BA | VW04104MAR |
| BZ04053BB | FD04358BA | FT99008CAL | SD04009BA | VW04107BA |
| BZ04056BA | FD07247GA | FT99008CAR | SD04009BB | VW04108BA |
| BZ07060GA | FD07247GB | FT99009CAL | SD04010BA | VW04108MA |
| CT04009MAL | FD07258GA | FT99009CAR | SD04010BB | VW04108MB |
| CT04009MAR | FD07280GA | FT99011CAL | SD04011BA | VW04116BA |
| CT04009MBL | FD07289GA | FT99011CAR | SD04011MAL | VW04119MAL |
| CT04009MBR | FD07308GA | FT99012CAL | SD04011MAR | VW04119MAR |
| CT04016BA | FD99157CAL | FT99012CAR | SD04013BA | VW04131BA |
| CT04016MAL | FD99157CAR | LN04003MA | SD04015BA | VW04131BB |
| CT04016MAR | FD99159CAL | LN04003MB | SD04015BB | VW04132BA |
| CT04017MA | FD99159CAR | LN04005BA | SD04015BC | VW04132BB |
| CT04017MB | FD99160CAL | LN04006BA | SD04015BD | VW04132BC |
| CT04018BA | FD99160CAR | OP04042BA | SD07005GAC | VW04132BD |
| CT04018MAL | FD99172CAL | OP04043BA | SD07005GAL | VW04133BA |
| CT04018MAR | FD99172CAR | OP04043BB | SD07005GAR | VW04133BB |
| CT04018MBL | FD99180CAL | OP04043BC | SD07006GA | VW04134BA |
| CT04018MBR | FD99180CAR | OP04043BD | SD07012GA | VW04134BB |
| CT04023BA | FT04029BB | OP04055BA | SD07013GA | VW04135BA |
| CT04024BA | FT04029BC | OP04056BA | SD07015GA | VW04135BB |
| CT07012GA | FT04029BD | OP04057BA | SD07016GAL | VW05010VA |
| CT07013GA | FT04031MA | OP04059BA | SD07016GAR | VW05012VA |
| CT99003CAL | FT04044BA | OP04062BA | SD99002CAL | VW05013VA |
| CT99003CAR | FT04045BA | OP04073BA | SD99002CAR | VW05014VA |
| CT99004CAL | FT04045MAC | OP07026GA | SD99003CAL | VW05015VA |
| CT99004CAR | FT04045MAL | OP07029GA | SD99003CAR | VW07069GA |
| DS01002MAL | FT04045MAR | OP99014CAL | ST04012BA | VW07072GA |
| DS01002MAR | FT04046BA | OP99014CAR | ST04013BA | VW07077GA |
| DS04250BA | FT04046BB | OP99014CBL | ST04017BA | VW99030CAL |
| DS04250BB | FT04046PAL | OP99014CBR | ST04017BB | VW99030CAR |
| DS04255BA | FT04046PAR | OP99015CAL | ST04018BA | VW99035CAL |
| DS04255BB | FT04046PBL | OP99015CAR | ST05002VA | VW99035CAR |
| DS04256BA | FT04046PBR | PG04024BA | TY04255BA | VW99045CAL |
| DS04256BB | FT04047BA | PG04024BB | TY04255MAL | VW99045CAR |
| DS04274BA | FT04048BA | PG04028BA | TY04255MAR | VW99046CAL |
| DS04275BA | FT04049BA | PG04028MAL | TY04255MBL | VW99046CAR |



Product Service

ZERTIFIKAT

Nr. B 12 04 68829 035

Zertifikatsinhaber:



TONG YANG GROUP
Tong Yang Industry Co. Ltd.

Tong Yang Industry Co. Ltd.

98. An Ho Rd.; Sec. 2
70967 Tainan
TAIWAN

**Produktions-
stätte(n):**

68829

Prüfzeichen:



Produkt:

**Anbauteile für KFZ aus Kunststoff
PKW Stoßfänger**

Modell(e):

PP
(Teilenummern siehe Anhang)

Kenndaten:

**Austauschstoßfänger und Grills für PKW aus PP
Montage und äußere Form entsprechend Originalteil**

Geprüft nach:

PPP 90015:2009

Das Produkt wurde auf freiwilliger Basis auf die Einhaltung der grundlegenden Anforderungen geprüft und kann mit dem oben abgebildeten Prüfzeichen gekennzeichnet werden. Eine Veränderung der Darstellung des Prüfzeichens ist nicht erlaubt. Die Übertragung eines Zertifikates durch den Zertifikatsinhaber an Dritte ist unzulässig. Umseitige Hinweise sind zu beachten.

Prüfbericht Nr.:

09-00040-CP-GBM-11

Datum, 2012-04-04

(Max Höhler)

Seite 1 von 2



Anlage zum Zertifikat Nr. B 11 12 68829 035



Product Service

Teile Nummern:

| | | | | |
|------------|------------|------------|------------|------------|
| AA04008BA | DS04281BA | FT04049BB | PG04028MAR | TY04255MBR |
| AA04009BA | DS07287GA | FT04050BA | PG04028MBL | TY04267BA |
| AA04010BA | DS99088CAL | FT04055BA | PG04028MBR | TY04268BA |
| AD04025BA | DS99088CAR | FT04059BC | PG04029BA | TY05032VAL |
| AD04032BA | FD04249BA | FT04059BD | PG04030BA | TY05032VAR |
| AT04015BA | FD04258BA | FT04059MA | RN04044BA | TY07350GA |
| BM04028BA | FD04261BA | FT05001VA | RN04044BB | TY07404GA |
| BM04032BA | FD04261MAL | FT05002VA | RN04046BA | TY99064CAL |
| BM04039BA | FD04261MAR | FT07018GA | RN04046MAL | TY99064CAR |
| BM04039BB | FD04305BA | FT07026GA | RN04046MAR | VV04009BA |
| BM04047BA | FD04306BA | FT07028GA | RN04052BA | VV04065MAL |
| BM04047BB | FD04307BA | FT07032GA | RN04052BB | VV04065MAR |
| BZ04028BA | FD04307PAL | FT07033GA | RN05007VA | VV04084BA |
| BZ04034BA | FD04307PAR | FT07041GA | RN07037GA | VV04085BB |
| BZ04035BA | FD04307PBL | FT07042GA | RN07050GA | VV04090MAL |
| BZ04035MAL | FD04307PBR | FT07043GA | RN07051GA | VV04090MAR |
| BZ04035MAR | FD04310BA | FT07043GB | RN99035CAL | VV04101BA |
| BZ04051BA | FD04319BA | FT07044GA | RN99035CAR | VV04101MAL |
| BZ04051BB | FD04325BA | FT07044GB | SD04007MAL | VV04101MAR |
| BZ04051BD | FD04353BA | FT99006CAL | SD04007MAR | VV04104MAL |
| BZ04053BA | FD04354BA | FT99006CAR | SD04008BA | VV04104MAR |
| BZ04053BB | FD04358BA | FT99008CAL | SD04009BA | VV04107BA |
| BZ04056BA | FD07247GA | FT99008CAR | SD04009BB | VV04108BA |
| BZ07060GA | FD07247GB | FT99009CAL | SD04010BA | VV04108MA |
| CT04009MAL | FD07258GA | FT99009CAR | SD04010BB | VV04108MB |
| CT04009MAR | FD07280GA | FT99011CAL | SD04011BA | VV04116BA |
| CT04009MBL | FD07289GA | FT99011CAR | SD04011MAL | VV04119MAL |
| CT04009MBR | FD07308GA | FT99012CAL | SD04011MAR | VV04119MAR |
| CT04016BA | FD99157CAL | FT99012CAR | SD04013BA | VV04131BA |
| CT04016MAL | FD99157CAR | LN04003MA | SD04015BA | VV04131BB |
| CT04016MAR | FD99159CAL | LN04003MB | SD04015BB | VV04132BA |
| CT04017MA | FD99159CAR | LN04005BA | SD04015BC | VV04132BB |
| CT04017MB | FD99160CAL | LN04006BA | SD04015BD | VV04132BC |
| CT04018BA | FD99160CAR | OP04042BA | SD07005GAC | VV04132BD |
| CT04018MAL | FD99172CAL | OP04043BA | SD07005GAL | VV04133BA |
| CT04018MAR | FD99172CAR | OP04043BB | SD07005GAR | VV04133BB |
| CT04018MBL | FD99180CAL | OP04043BC | SD07006GA | VV04134BA |
| CT04018MBR | FD99180CAR | OP04043BD | SD07012GA | VV04134BB |
| CT04023BA | FT04029BB | OP04055BA | SD07013GA | VV04135BA |
| CT04024BA | FT04029BC | OP04056BA | SD07015GA | VV04135BB |
| CT07012GA | FT04029BD | OP04057BA | SD07016GAL | VV05010VA |
| CT07013GA | FT04031MA | OP04059BA | SD07016GAR | VV05012VA |
| CT99003CAL | FT04044BA | OP04062BA | SD99002CAL | VV05013VA |
| CT99003CAR | FT04045BA | OP04073BA | SD99002CAR | VV05014VA |
| CT99004CAL | FT04045MAC | OP07026GA | SD99003CAL | VV05015VA |
| CT99004CAR | FT04045MAL | OP07029GA | SD99003CAR | VV07069GA |
| DS01002MAL | FT04045MAR | OP99014CAL | ST04012BA | VV07072GA |
| DS01002MAR | FT04046BA | OP99014CAR | ST04013BA | VV07077GA |
| DS04250BA | FT04046BB | OP99014CBL | ST04017BA | VV99030CAL |
| DS04250BB | FT04046PAL | OP99014CBR | ST04017BB | VV99030CAR |
| DS04255BA | FT04046PAR | OP99015CAL | ST04018BA | VV99035CAL |
| DS04255BB | FT04046PBL | OP99015CAR | ST05002VA | VV99035CAR |
| DS04256BA | FT04046PBR | PG04024BA | TY04255BA | VV99045CAL |
| DS04256BB | FT04047BA | PG04024BB | TY04255MAL | VV99045CAR |
| DS04274BA | FT04048BA | PG04028BA | TY04255MAR | VV99046CAL |
| DS04275BA | FT04049BA | PG04028MAL | TY04255MBL | VV99046CAR |