



Product Service

CERTIFICATE

No. B 10 07 68829 013

Holder of Certificate: Tong Yang Industry Co. Ltd.
TONG YANG GROUP
Tong Yang Industry Co. Ltd.98. An Ho Rd.; Sec. 2
70967 Tainan
TAIWAN
Production Facility(ies): 68829

Certification Mark:

Product: Adhered units for vehicles, plastic parts
Passenger car bumpers

Model(s): PP
(Part No. see attachment)


Parameters: Aftermarket bumper for passenger car made of PP
Fittment and shape equal to original equipment

Tested according to: PPP 90015:2009

The product was tested on a voluntary basis and complies with the essential requirements. The certification mark shown above can be affixed on the product. It is not permitted to alter the certification mark in any way. In addition the certification holder must not transfer the certificate to third parties. See also notes overleaf.

Test report no.: 09-00040-CP-GBM-05

Date, 2010-07-22


(Max Höhler)

Page 1 of 2





Product Service

Attachment to Certificate B 10 07 68829 013

Holder of Certificate: Tong Yang Industry Co. Ltd.

Passenger car bumpers Part No.:

AA04008BA	FD04310BA	FT07028GA	PG04028MAR	TY04255MBL
AA04009BA	FD07247GA	FT07032GA	PG04028MBL	TY04255MBR
BM04028BA	FD07247GB	FT07033GA	PG04028MBR	TY04267BA
BZ04028BA	FD07258GA	FT99006CAL	PG04029BA	TY99064CAL
BZ04034BA	FD07280GA	FT99006CAR	RN04044BA	TY99064CAR
BZ04035BA	FD99157CAL	FT99008CAL	RN04044BB	VW04065MAL
BZ04035MAL	FD99157CAR	FT99008CAR	RN04046BA	VW04065MAR
BZ04035MAR	FD99159CAL	FT99009CAL	RN04046MAL	VW04090MAL
BZ04051BA	FD99159CAR	FT99009CAR	RN04046MAR	VW04090MAR
BZ04051BD	FD99160CAL	LN04003MA	RN04052BA	VW04101BA
CT04016BA	FD99160CAR	LN04003MB	RN04052BB	VW04101MAL
CT04016MAL	FT04029BB	LN04005BA	RN05007VA	VW04101MAR
CT04016MAR	FT04029BC	LN04006BA	RN07037GA	VW04104MAL
CT04017MA	FT04029BD	OP04042BA	RN99035CAL	VW04104MAR
CT04017MB	FT04031MA	OP04043BA	RN99035CAR	VW04107BA
CT04018BA	FT04044BA	OP04043BB	SD04007MAL	VW04108BA
CT07012GA	FT04045BA	OP04043BC	SD04007MAR	VW04108MA
CT99003CAL	FT04045MAC	OP04043BD	SD04009BA	VW04108MB
CT99003CAR	FT04045MAL	OP04055BA	SD04009BB	VW04116BA
CT99004CAL	FT04045MAR	OP04056BA	SD04010BA	VW04119MAL
CT99004CAR	FT04046BA	OP04057BA	SD04010BB	VW04119MAR
DS04250BA	FT04046BB	OP04059BA	SD04011BA	VW05010VA
DS04250BB	FT04046PAL	OP04062BA	SD04011MAL	VW05012VA
DS04255BA	FT04046PAR	OP07026GA	SD04011MAR	VW05013VA
DS04255BB	FT04046PBL	OP07029GA	SD07005GAC	VW05014VA
DS04256BA	FT04046PBR	OP99014CAL	SD07005GAL	VW05015VA
DS04256BB	FT04047BA	OP99014CAR	SD07005GAR	VW07069GA
DS04275BA	FT04048BA	OP99014CBL	SD07006GA	VW07072GA
DS07287GA	FT04049BA	OP99014CBR	SD07013GA	VW07077GA
FD04249BA	FT04049BB	OP99015CAL	ST04012BA	VW99030CAL
FD04258BA	FT04050BA	OP99015CAR	ST04013BA	VW99030CAR
FD04261BA	FT05001VA	PG04024BA	ST05002VA	VW99035CAL
FD04261MAL	FT05002VA	PG04024BB	TY04255BA	VW99035CAR
FD04261MAR	FT07018GA	PG04028BA	TY04255MAL	
FD04306BA	FT07026GA	PG04028MAL	TY04255MAR	