

**MEYDAN NO: 760-2061A**



Product Service

# CERTIFICATE

**No. B 12 04 68829 035**

**Holder of Certificate: Tong Yang Industry Co. Ltd.**



**TONG YANG GROUP**  
**Tong Yang Industry Co. Ltd.**

98. An Ho Rd.; Sec. 2  
70967 Tainan  
TAIWAN

**Production Facility(ies):** 68829

**Certification Mark:**



**Product:** Adhered units for vehicles, plastic parts  
Passenger car bumpers

**Model(s):** PP  
(Part No. see attachment)

**Parameters:** Aftermarket bumper and grills for passenger car made of PP  
Fittment and shape equal to original equipment

**Tested according to:** PPP 90015:2009

The product was tested on a voluntary basis and complies with the essential requirements. The certification mark shown above can be affixed on the product. It is not permitted to alter the certification mark in any way. In addition the certification holder must not transfer the certificate to third parties. See also notes overleaf.

**Test report no.:** 09-00040-CP-GBM-11

**Date,** 2012-04-04

(Max Höhler)

Page 1 of 2





Product code:

Product Service

AA04008BA	DS04281BA	FT04049BB	PG04028MAR	TY04255MBR
AA04009BA	DS07287GA	FT04050BA	PG04028MBL	TY04267BA
AA04010BA	DS99088CAL	FT04055BA	PG04028MBR	TY04268BA
AD04025BA	DS99088CAR	FT04059BC	PG04029BA	TY05032VAL
AD04032BA	FD04249BA	FT04059BD	PG04030BA	TY05032VAR
AT04015BA	FD04258BA	FT04059MA	RN04044BA	TY07350GA
BM04028BA	FD04261BA	FT05001VA	RN04044BB	TY07404GA
BM04032BA	FD04261MAL	FT05002VA	RN04046BA	TY99064CAL
BM04039BA	FD04261MAR	FT07018GA	RN04046MAL	TY99064CAR
BM04039BB	FD04305BA	FT07026GA	RN04046MAR	VV04009BA
BM04047BA	FD04306BA	FT07028GA	RN04052BA	VW04065MAL
BM04047BB	FD04307BA	FT07032GA	RN04052BB	VW04065MAR
BZ04028BA	FD04307PAL	FT07033GA	RN05007VA	VW04084BA
BZ04034BA	FD04307PAR	FT07041GA	RN07037GA	VW04085BB
BZ04035BA	FD04307PBL	FT07042GA	RN07050GA	VW04090MAL
BZ04035MAL	FD04307PBR	FT07043GA	RN07051GA	VW04090MAR
BZ04035MAR	FD04310BA	FT07043GB	RN99035CAL	VW04101BA
BZ04051BA	FD04319BA	FT07044GA	RN99035CAR	VW04101MAL
BZ04051BB	FD04325BA	FT07044GB	SD04007MAL	VW04101MAR
BZ04051BD	FD04353BA	FT99006CAL	SD04007MAR	VW04104MAL
BZ04053BA	FD04354BA	FT99006CAR	SD04008BA	VW04104MAR
BZ04053BB	FD04358BA	FT99008CAL	SD04009BA	VW04107BA
BZ04056BA	FD07247GA	FT99008CAR	SD04009BB	VW04108BA
BZ07060GA	FD07247GB	FT99009CAL	SD04010BA	VW04108MA
CT04009MAL	FD07258GA	FT99009CAR	SD04010BB	VW04108MB
CT04009MAR	FD07280GA	FT99011CAL	SD04011BA	VW04116BA
CT04009MBL	FD07289GA	FT99011CAR	SD04011MAL	VW04119MAL
CT04009MBR	FD07308GA	FT99012CAL	SD04011MAR	VW04119MAR
CT04016BA	FD99157CAL	FT99012CAR	SD04013BA	VW04131BA
CT04016MAL	FD99157CAR	LN04003MA	SD04015BA	VW04131BB
CT04016MAR	FD99159CAL	LN04003MB	SD04015BB	VW04132BA
CT04017MA	FD99159CAR	LN04005BA	SD04015BC	VW04132BB
CT04017MB	FD99160CAL	LN04006BA	SD04015BD	VW04132BC
CT04018BA	FD99160CAR	OP04042BA	SD07005GAC	VW04132BD
CT04018MAL	FD99172CAL	OP04043BA	SD07005GAL	VW04133BA
CT04018MAR	FD99172CAR	OP04043BB	SD07005GAR	VW04133BB
CT04018MBL	FD99180CAL	OP04043BC	SD07006GA	VW04134BA
CT04018MBR	FD99180CAR	OP04043BD	SD07012GA	VW04134BB
CT04023BA	FT04029BB	OP04055BA	SD07013GA	VW04135BA
CT04024BA	FT04029BC	OP04056BA	SD07015GA	VW04135BB
CT07012GA	FT04029BD	OP04057BA	SD07016GAL	VW05010VA
CT07013GA	FT04031MA	OP04059BA	SD07016GAR	VW05012VA
CT99003CAL	FT04044BA	OP04062BA	SD99002CAL	VW05013VA
CT99003CAR	FT04045BA	OP04073BA	SD99002CAR	VW05014VA
CT99004CAL	FT04045MAC	OP07026GA	SD99003CAL	VW05015VA
CT99004CAR	FT04045MAL	OP07029GA	SD99003CAR	VW07069GA
DS01002MAL	FT04045MAR	OP99014CAL	ST04012BA	VW07072GA
DS01002MAR	FT04046BA	OP99014CAR	ST04013BA	VW07077GA
DS04250BA	FT04046BB	OP99014CBL	ST04017BA	VW99030CAL
DS04250BB	FT04046PAL	OP99014CBR	ST04017BB	VW99030CAR
DS04255BA	FT04046PAR	OP99015CAL	ST04018BA	VW99035CAL
DS04255BB	FT04046PBL	OP99015CAR	ST05002VA	VW99035CAR
DS04256BA	FT04046PBR	PG04024BA	TY04255BA	VW99045CAL
DS04256BB	FT04047BA	PG04024BB	TY04255MAL	VW99045CAR
DS04274BA	FT04048BA	PG04028BA	TY04255MAR	VW99046CAL
DS04275BA	FT04049BA	PG04028MAL	TY04255MBL	VW99046CAR



Product Service

# ZERTIFIKAT

Nr. B 12 04 68829 035

**Zertifikatsinhaber:**



TONG YANG GROUP  
*Tong Yang Industry Co. Ltd.*

**Tong Yang Industry Co. Ltd.**

98. An Ho Rd.; Sec. 2  
70967 Tainan  
TAIWAN

**Produktions-  
stätte(n):**

68829

**Prüfzeichen:**



**Produkt:**

**Anbauteile für KFZ aus Kunststoff  
PKW Stoßfänger**

**Modell(e):**

PP  
(Teilenummern siehe Anhang)

**Kenndaten:**

**Austauschstoßfänger und Grills für PKW aus PP  
Montage und äußere Form entsprechend Originalteil**

**Geprüft nach:**

PPP 90015:2009

Das Produkt wurde auf freiwilliger Basis auf die Einhaltung der grundlegenden Anforderungen geprüft und kann mit dem oben abgebildeten Prüfzeichen gekennzeichnet werden. Eine Veränderung der Darstellung des Prüfzeichens ist nicht erlaubt. Die Übertragung eines Zertifikates durch den Zertifikatsinhaber an Dritte ist unzulässig. Umseitige Hinweise sind zu beachten.

**Prüfbericht Nr.:**

09-00040-CP-GBM-11

**Datum,** 2012-04-04

( Max Höhler )

Seite 1 von 2



Anlage zum Zertifikat Nr. B 11 12 68829 035



Product Service

Teile Nummern:

AA04008BA	DS04281BA	FT04049BB	PG04028MAR	TY04255MBR
AA04009BA	DS07287GA	FT04050BA	PG04028MBL	TY04267BA
AA04010BA	DS99088CAL	FT04055BA	PG04028MBR	TY04268BA
AD04025BA	DS99088CAR	FT04059BC	PG04029BA	TY05032VAL
AD04032BA	FD04249BA	FT04059BD	PG04030BA	TY05032VAR
AT04015BA	FD04258BA	FT04059MA	RN04044BA	TY07350GA
BM04028BA	FD04261BA	FT05001VA	RN04044BB	TY07404GA
BM04032BA	FD04261MAL	FT05002VA	RN04046BA	TY99064CAL
BM04039BA	FD04261MAR	FT07018GA	RN04046MAL	TY99064CAR
BM04039BB	FD04305BA	FT07026GA	RN04046MAR	VV04009BA
BM04047BA	FD04306BA	FT07028GA	RN04052BA	VV04065MAL
BM04047BB	FD04307BA	FT07032GA	RN04052BB	VV04065MAR
BZ04028BA	FD04307PAL	FT07033GA	RN05007VA	VV04084BA
BZ04034BA	FD04307PAR	FT07041GA	RN07037GA	VV04085BB
BZ04035BA	FD04307PBL	FT07042GA	RN07050GA	VV04090MAL
BZ04035MAL	FD04307PBR	FT07043GA	RN07051GA	VV04090MAR
BZ04035MAR	FD04310BA	FT07043GB	RN99035CAL	VV04101BA
BZ04051BA	FD04319BA	FT07044GA	RN99035CAR	VV04101MAL
BZ04051BB	FD04325BA	FT07044GB	SD04007MAL	VV04101MAR
BZ04051BD	FD04353BA	FT99006CAL	SD04007MAR	VV04104MAL
BZ04053BA	FD04354BA	FT99006CAR	SD04008BA	VV04104MAR
BZ04053BB	FD04358BA	FT99008CAL	SD04009BA	VV04107BA
BZ04056BA	FD07247GA	FT99008CAR	SD04009BB	VV04108BA
BZ07060GA	FD07247GB	FT99009CAL	SD04010BA	VV04108MA
CT04009MAL	FD07258GA	FT99009CAR	SD04010BB	VV04108MB
CT04009MAR	FD07280GA	FT99011CAL	SD04011BA	VV04116BA
CT04009MBL	FD07289GA	FT99011CAR	SD04011MAL	VV04119MAL
CT04009MBR	FD07308GA	FT99012CAL	SD04011MAR	VV04119MAR
CT04016BA	FD99157CAL	FT99012CAR	SD04013BA	VV04131BA
CT04016MAL	FD99157CAR	LN04003MA	SD04015BA	VV04131BB
CT04016MAR	FD99159CAL	LN04003MB	SD04015BB	VV04132BA
CT04017MA	FD99159CAR	LN04005BA	SD04015BC	VV04132BB
CT04017MB	FD99160CAL	LN04006BA	SD04015BD	VV04132BC
CT04018BA	FD99160CAR	OP04042BA	SD07005GAC	VV04132BD
CT04018MAL	FD99172CAL	OP04043BA	SD07005GAL	VV04133BA
CT04018MAR	FD99172CAR	OP04043BB	SD07005GAR	VV04133BB
CT04018MBL	FD99180CAL	OP04043BC	SD07006GA	VV04134BA
CT04018MBR	FD99180CAR	OP04043BD	SD07012GA	VV04134BB
CT04023BA	FT04029BB	OP04055BA	SD07013GA	VV04135BA
CT04024BA	FT04029BC	OP04056BA	SD07015GA	VV04135BB
CT07012GA	FT04029BD	OP04057BA	SD07016GAL	VV05010VA
CT07013GA	FT04031MA	OP04059BA	SD07016GAR	VV05012VA
CT99003CAL	FT04044BA	OP04062BA	SD99002CAL	VV05013VA
CT99003CAR	FT04045BA	OP04073BA	SD99002CAR	VV05014VA
CT99004CAL	FT04045MAC	OP07026GA	SD99003CAL	VV05015VA
CT99004CAR	FT04045MAL	OP07029GA	SD99003CAR	VV07069GA
DS01002MAL	FT04045MAR	OP99014CAL	ST04012BA	VV07072GA
DS01002MAR	FT04046BA	OP99014CAR	ST04013BA	VV07077GA
DS04250BA	FT04046BB	OP99014CBL	ST04017BA	VV99030CAL
DS04250BB	FT04046PAL	OP99014CBR	ST04017BB	VV99030CAR
DS04255BA	FT04046PAR	OP99015CAL	ST04018BA	VV99035CAL
DS04255BB	FT04046PBL	OP99015CAR	ST05002VA	VV99035CAR
DS04256BA	FT04046PBR	PG04024BA	TY04255BA	VV99045CAL
DS04256BB	FT04047BA	PG04024BB	TY04255MAL	VV99045CAR
DS04274BA	FT04048BA	PG04028BA	TY04255MAR	VV99046CAL
DS04275BA	FT04049BA	PG04028MAL	TY04255MBL	VV99046CAR